



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

C-5

Date Recovered: 24 APRIL 1999Corner Description: SE
SW COR - NE 1/4 6-22-7Corner Recovered by: A. GUERIN & D. WIMMERSITE MAPMaterial Found: STONE 0.2 COVER

- References:
1. #6 REBAR SET AT PAVEMENT EDGE.
 2. _____
 3. _____
 4. _____
 5. _____
 6. _____

Condition of Corner: EXCELLENT

IRON ROD FOUND ON NORTH SIDE OF STONE AS WITNESS.
PK NAIL SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

