



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 25 MARCH 1996

C-21

Corner Description: NE COR- SE 1/4 2-22-8Corner Recovered by: A. GUERIN & D. WHITNERMaterial Found: GRANITE STONE 0.8' COVER

- References:
1. 8" IRON POST
 2. 3" IRON POST
 3. CORNER OF BRICK ON HOUSE
 4. CONCRETE POST
 5. NAIL SET IN UTILITY POLE
 6. HOUSE FOUNDATION

Condition of Corner: EXCELLENT

TRACK SPIKE WITH CAP SET.

SMALL PK NAILS SET AT 6.0' WEST, N.E. & S.E. OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # 50198

