



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 12 APRIL 1991Corner Description: NE COR- SE $\frac{1}{4}$ S-22-8Corner Recovered by: A. GUERIN- D. WILMERMaterial Found: GRANITE STONE @ SURFACE

- References:
1. #4 REBAR SET
 2. #4 REBAR SET
 3. WOOD POST
 4. #4 REBAR SET
 5.
 6.

Condition of Corner: GOOD

CHISEL CUT FOUND ON STONE MARKED $\frac{1}{4}$ S ON NORTH SIDE.
#4 REBAR SET ON SOUTH SIDE OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered OR Restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
REGISTERED
NO. 30198
STATE OF INDIANA
Land Surveyor